

## **INSPECTION REPORT**

Pre-Shipment Inspection (SAMPLE REPORT)

INSPECTION INFORMATION						
Client	ABCDE	BCDE				
Supplier	ABCDE	BCDE				
Factory	ABCDE					
Inspection Instruction	MSTP-M-004-M7	1STP-M-004-M7				
P.O. No.	123456, 123456	P.O. Quantity	999 Pieces			
Item No.	Dining Table/Chair	Sampling Plan	ISO2859: Single, Normal			
Inspection Date	XXXXXX	Inspection Level	G-II			
Inspection Sequence	Uploading inspection	Sample Size	100 Pieces			
Inspection Location	XXXXXX	AQL	Critical: 0, Major:2.5, Minor:4.0			
Product Description	Dinning Table					



INSPECTION RE	SULT SUMMARY		
Category	Conform	Not Conform	Pending
1.Quantity	Х		
2.Workmanship	Х		
3.Style, Color & Documentation	Х		
4.Field Test & Measurement			Х
5.Shipping Mark & Packaging	Х		
OVERALL CONCLUSION	PENDING for	client's evaluation	

Approved by M7TP Supervisor:	xxxxx

This report reflects the facts as recorded by M7TP at the time and place of inspection. It does not relieve the manufacturers from their contractual obligations nor prejudice client's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter.

## SPECIAL ATTENTION POINT (SAP)

1	Quantity	NIL
		1
2	Workmanship	NIL
3	Style, Color & Documentation	NIL
4	Field Test & Measurement	
4.1	The factory did not allow us to conduct breakage	tempered glass test and carton drop test.

### 5

Shipping Mark & Packaging


NIL

# **INSPECTION DETAILS**

1. Quantity				Conform				
	lta en Nia	P.O. Qty	Shipment Qty		Packed Qty		Sample Size	
P.O. No.	Item No.	(Piece)	(Piece)	(Carton)	(Piece)	(Carton)	(Piece)	(Carton)
374207	Dining Table	115	115	230	115	230	11	22
374208	Dining Chair	690	690	345	690	345	69	35
	Total	805	805	575	805	575	80	57

2.Workmanship				
Defects Description		Critical	Major	Minor
Item#: Dining Table Sample size:11 pieces				
Broken at leg(0.6cm)			1	
Convex mark at leg(0.3~0.5cm)				2
Item#:Dining Chair Sample size:69 pieces				
Rusty mark at hole(1cm)			1	
Scratched mark at leg(0.5~1.5cm)				2
	Total Found:	0	2	4
	Allowed:	0	5	7
	Sample Size:	80	80	80

### **Defect Photos**



Report No: M-12345

3. Style, Color & Documentation	e, Color & Documentation Conform		
DESCRIPTION	Conform	Not Conform	Pending
The inspected samples were consistent with	-	-	-
Purchase Order	Х		
Product Specification	Х		
Instruction manual and Document Verification	-	-	-
Instruction manual in English.			

4. Field Test & Measurement					Pending		
	ltem	Specification	Sample Size	Conform	Not Conform	Pending	
4.1	Product dimension check	-	3 Sample/item	Х			
4.2	Product weight check	-	3 Sample/item	Х			
4.3	Barcode scanning test	-	3 Sample/item	Х			
4.4	Smell check	-	3 Sample/item	Х			
4.5	Rub and tape test for Painting	-	3 Sample/item	Х			
4.6	Assembly check	-	3 Sample/item	Х			
4.7	Loading test	-	3 Sample/item	Х			
4.8	Stability check	-	3 Sample/item	Х			
4.9	Breakage tempered glass test	-	1 Sample			Х	
4.10	Carton dimension check	-	1 Carton/Item	Х			
4.11	Carton weight check	-	1 Carton/Item	Х			
4.12	Quantity per carton check	-	2 Cartons/Item	Х			
4.13	Carton drop test	-	1 Carton			Х	

Checking Item	Specification	Result
	Item#: Dining Table	
Carton dimension (cm)	-	Glass: 153.3x92.8x3 Leg: 122.5x66x8.3
Carton weight (kg)	-	Glass: 27.76 Leg: 7.86
Product weight (kg)	-	32.38, 32.64, 32.50
Product size (mm)	1500x900x760	1497x898x748, 1497x898x745, 1497x898x747
Glass thickness (mm)	-	8, 8, 8
	Item#: Dining Chair	
Carton dimension (cm)	-	61.5x48x56.5
Carton weight (kg)	-	9.68
Product weight (kg)	-	3.94, 3.90, 3.94
Product size (cm)	Depth x Width x Height x Seat H	52.5x44.5x84x45, 52.7x44.5x84.5x45 52.5x44.8x84.3x45.3

# Report No: M-12345 S. Shipping Mark & Packaging Conform 5.1 Shipping mark photos 5.1 Shipping mark photos 5.1 Shipping mark photos Image: Screption BillAcAs Image: Scre



Remark: Only item number Dining Chair is listed here for your reference. For other items please refer to photos attached.

Packaging Description:


- 1 piece of product was packed into a polybag.
- 2 pieces of products were packed into a 5-ply corrugated export carton.
- Export carton was sealed with gummed tape.

6. Ref	erence Note
6.1	The weight of carton was measured by the apparatus without calibration which was provided by the factory. Our inspector required the factory to calibrate the apparatus regularly.
6.2	The inspected cartons were not sealed because the factory did not repack them immediately after inspection.
6.3	Manufacturer did not allow us to draw any production sample for reference.
6.4	Our inspector required the factory to repair all defective samples before shipment.
6.5	Draft report has been provided to the factory and defective points have been explained as well.


### 7. Photos



Report No: M-12345




Report No: M-12345



Report No: M-12345




Report No: M-12345




Report No: M-12345



Report No: M-12345



Report No: M-12345




Report No: M-12345




Report No: M-12345



Report No: M-12345



Report No: M-12345



Report No: M-12345

